ECS Configuration Change Request					Page 1 of	Page 1 of Page(s)			
1. Originator	2. Log Date:	3. CCR #:		4. Rev	5. Tel:		6. Rm #:	7. Dept.	
Rajesh Dharia	12 JUL 00	00-0	723	((301) 925-0498	8	3204E	Rel. Dev	
8. CCR Title: Install 2.1 GB external drive on delware_srvr									
9. Originator Signature/Date			10. C	lass	s 11. Type: 12. Need Date: 7/17/00				
Rajish Dhame 7/10/10			718		CCR				
13. Øffice Manager Signature/Date			14. Category o		of Change:	f Change: 15. Priority: (If "Emergency" fill in Block 28).		• •	
M. Myandes 7/11/00			EDF (F	RTSC)	Routine				
16. Documentation/Drawings Impacted:			17. Schedule 18. Cl(s) Affected:						
N/A									
19. Release Affected by this Change: 20. Date due t				o Customer: 21. Estimated Cost:					
5B				None - Under 100K					
22. Source Reference: NCR (attach) Action Item Tech Ref. GSFC Other: Email from Michelle Johnson									
23. Problem: (use additional Sheets if necessary) CCR # 00-0688, title: Create and drop registry database for development on delware_srvr, which was approved on 6/28/00 can not									
be implemented due to insufficient disk space (due to space allocated to security server). In order to implement the CCR 00-0688 it									
requires an external drive to be added on delaware_srvr.									
24. Proposed Solution: (use additional sheets if necessary)									
Add an external 2.1 GB drive, EIN # 1824 on delaware_srvr for database needs.									
25. Alternate Solution: (use additional sheets if necessary)									
N/A									
26. Consequences if Change(s) are not approved: (use additional sheets if necessary)									
Previously submitted CCR 00-0688 can not be completed without additional space needed on delaware_srvr									
27. Justification for Emergency (If Block 15 is "Emergency"):									
28. Site(s) Affected: SEDF PVC VATC EDC GSFC LARC NSIDC SMC AK JPL EOC DDG Test Cell Other									
29. Board Comments:				30. \	Work Assigned T	o:	31. CCR C	losed Date:	
32. EDF/SCDV CCB Chair (om. Disapproved	Wit	thdraw Fwo	d/ESDIS ERB					
1. h As C	7/12/00	position: Ap	vd/ECS	11.3	16				
33. M&O CCB Chair (Sign/I		position: Ap		Арр/Сс	om. Disapproved	l Wi	ithdraw Fwo	/ESDIS ERB	
		Fv	vd/ECS						
34. ECS CCB Chair (Sign/D	ate): Disp	osition: App	proved	App/Co	m. Disapproved	iW t	ithdraw Fw	d/ESDIS ERB	
Fwd/ESDIS									

ORIGINAL

CM01JA00

ECS/EDF/SCDV/M&O